2 March 1994



COMMERCIAL & CONSUMER CUSTOMER RESPONSE UNIT

8/242 EXHIBITION STREET MELBOURNE VIC 3000

Australia

Telephone

(03) 634-5736

Facsimile

(03) 634-8441

Detective Superintendent
Jeff Penrose
AUSTRALIAN FEDERAL POLICE
SPECIAL REFERENCE INVESTIGATION
PO BOX 401
CANBERRA CITY A.C.T. 2601

Dear Detective Superintendent

RE: A.F.P. ENQUIRY

I refer to an article which appeared in the Australian Financial Review on Friday 25 February 1994 headed "Telecom minute reveals another bugging, small businessman tells police". (Copy attached)

The article stated, inter alia, that Mr Alan Smith had referred an alleged bugging incident to an A.F.P. officer the day before during five hours of questioning.

The article refers to a Telecom minute obtained under F.O.I. which indicates a series of tests were conducted on Mr Smith's telephone network in late November to determine whether the reported faults were legitimate. The article goes on to say that Mr Smith said he had never given Telecom permission to conduct such monitoring.

I have enquired into the circumstances surrounding the incident referred to and consider the outcome of that enquiry sufficiently disturbing so as to put certain information to you.

Firstly, a search of the information provided to Alan Smith under F.O.I. revealed a document headed FAX INVESTIGATION. A copy is attached hereto for your perusal. The background to that document is as follows.

Mr Smith made several reports of faulty fax transmissions during late October and the first 3 weeks of November 1993.

Ross Anderson of Warrnambool Customer Operations Group attended Mr Smith's property and conducted tests on Mr Smith's machine in conjunction with Waverley Business Service Centre and National Fax Support Centre. Some minor mis-operations were detected, but no difficulties were experienced sending faxes between machines in the test centres and Mr Smith's machine.

A5398

9F

 $\sqrt{}$

Ross Anderson attended Mr Smith's property on 23.11.93 following a fault report. During the visit the fax machine rang once and stopped. No fax was received. A call was received immediately after on Mr Smith's voice line. It was Graham Schorer calling to inform Mr Smith he had attempted to send a fax from his machine at Golden Messenger to Mr Smith and had experienced a failure.

Ross Anderson made arrangements with Bert Lopes to test the Golden Messenger machine from the Waverley BSC. This was completed and no faults or protocol errors were detected between the Golden Messenger machine and the Waverley BSC.

Bert Lopes who had carried out the test on both machines spoke to Ross Anderson and concluded that there may be a protocol problem between the two machines.

In order to detect protocol problems between machines it is necessary to send test patterns between me machines and record the signals sent from machine to machine so that they can be analysed in conjunction with computer equipment at the Business Service Centre or Fax Support.

Arrangements were made with Mr Smith for Ross Anderson to attend Cape Bridgewater

Holiday Camp and Bert Lopes made arrangements with Mr Schorer to attend Golden

Messenger on 29 November 1993 to record test patterns and signals between the machines.

The procedure being carried out was explained in detail to both Mr Smith and Mr Schorer and it was explained to Mr Smith that tape recordings of the protocol and the test patterns would be made and subsequently deciphered to determine any interworking problem with the machines.

Mr Schorer and Mr Smith were both present during the test procedure.

Bert Lopes needed to leave Mr Schorer's premises temporarily during testing to put money in a parking meter. On his return one fax transmission had failed. Bert sent a total of 20 fax transmissions and there were no other failures.

Analysis of signalling between the machines gave no indication as to why the one transmission failed.

Mr Smith was given the originals of the test transmissions and the fax log by Ross Anderson before he left the premises that day.

I also attach a statement prepared by the two technicians involved in the testing. You will note that both state that they informed both Mr Schorer and Mr Smith of the proposed testing process and of the fact that the protocol and the test pattern would be taped for subsequent analysis. You will also note that Ross Anderson provided Mr Smith with the original test faxes and the Receive Transmit Journal.

Finally, I attach a copy of a minute prepared by Mr Bruce Pendlebury, the Difficult Network Fault Co-ordinator, Telecom Commercial Vic/Tas Region. The minute relates to a phone conversation he had with Mr Smith on 28 February 1994. It would seem that Mr Smith now is requesting Telecom to tape monitor his fax machine.

If, as the newspaper article suggests, Mr Smith has alleged to the Federal Police that a "bugging" incident took place, this is a matter of extreme concern to Telecom. Telecom is of the view that the circumstances outlined above cannot on any reasonable interpretation be labelled a "bugging". No customers' conversations or transmissions were taped. Both customers were fully aware of the testing procedure and the fact that the test transmissions were to be taped. Both gave their complete informed consent to the testing.

The statement made in the article that Mr Smith said he had never given Telecom permission do not accord with events as recorded in the attached statements.

The staff involved in this particular incident are of course available to assist you in your enquiries.

Yours sincerely

I Row

CORPORATE SOLICITOR

9 A

Facsimile

Telecom

Network Products

Melbourne, 3000 ··

Australia

k 01489

Telephone

Facsimile -

National Facsimile Support Centre

03 634 6993

03 640 0997

23 rd Floor 242 Exhibition St.

To

T DT . O

Ross Anderson

Company

Telecom Portland

Facsimile

055 236 56

From

Alan Barrow

P.T.T.O.1

Subject

COT Case

-1--01-

Date

29 October 1993

Ross.

The following pages are copies of my fax machines journal and the protocol printouts of failed calls.

On the date of 28-OCT-93 we were trying to create a line failure condition that would re-produce the same error on the transmitting machine and no record on the receiving Mitsubishi machine (055 267 230). The reason for this was to show that a sending fax machine could get to the point of transmitting a page to the Mitsubishi fax machine without the Mitsubishi machine having any record of the call.

The COT case call in question was the 27-10-93 at 10:46 on the journal (it is suspected that the clock in this machine is approx 1 Hour-and 15 Minutes in error). The duration of the transmitting machine page of 2:21 minutes suggests that the call failed at the end of the page, possibly when requesting a reply from the receiving end. The presence of the ID in the journal of "055 267230" indicates the call was connected to the Mitsubishi fax machine in question. The receiving Machine has no matching entry in its journal for this call.

A call was placed to 055 267230 and connectivity terminated at the beginning of the page but this resulted in an error of NG in the journal along with the ID of the calling fax machine. The only way to reproduce the conditions experienced above was to interrupt the power on the receiving Mitsibishi fax machine. This would result in an entry in the transmitting machine and no entry whatsoever in the receiving Mistubishi machine.

During testing the Mitsubishi fax machine, some alarming patterns of behaviour were noted, these affecting both transmission and reception. Even on calls that were not tampered with the fax machine displayed signs of locking up and behaving in a manner not in accordance with the relevant CCITT Group 3 fax rules. A half A4 page being transmitted from this machine resulted in a blank piece of paper 4cm long, the relevant protocol printout in sample #2 shows that the machine sent the correct protocol at the end of the page. Even if the page was sent upside down the time and date and company name should have still appeared on the top of the page, it wasn't. During a received call the machine failed to respond at the end of the page even though it had received the entire page (sample #3). The Mitsubishi fax machine remained in the locked up state for a further 2 minutes after the call had terminated, eventually advancing the page out of the machine.

Regards Alan Barrow





K03750

PROTOCOL MONITOR

DATE/TIME LOCAL TERMINAL 1D. LOCAL TERMINAL NAME COMPANY LOGO 28-10-93 12:37 FM 6130400997 03 6400997

*** SEND ***

	REMOTE STATION	START	TIME	DURATION	#PAGES	MODE	RESULTS
1	055 267230	28-10-93	12:36 PM	0.47.	1		COMPLETED 9600
'	•••						13000

COM:0 G3S:0 G3R:0 ECM:0 CSI:1 CIG:0 CFG:4 RHP:0 LGO:0 THP:1 W/B:74 EQL:08

VERSION: KM1=X01. 09 KM2=R01. 09 KSP= 02. 00 KCP=R04. 03

APSE	LOCAL	REMOTE NSF	FCF 20	FIF 00000580004EB80008252020202020202020202020202020 20006000180B
3-76	š	← CSI ← DIS	40 80	3033323736322035353020202020202020202020 004EB800
4 * 4 ? 5 * 7 0 6 * 4 6	TSI	\rightarrow	43 83	0045A800
6 " 83 7 " 08 7 " 08	TRN TRN	.→ → → →		
5"59 9"97		← CFR	84	
10°26	TRN TRN	→ → →		
11"52 33"03 34"31	XIA -	$\overrightarrow{\Rightarrow}$	2F	2 very slow response
38"76 43"21	1 EOP	→ ← MCF	2F 2F 2F	(vary Sibil .)
44"57		→ MCF	8C FB	}

XEROX Telecopier 7017

PROTOCOL MONITOR

DATE TIME LOCAL TERMINAL ID. LOCAL TERMINAL NAME COMPANY LOGO 28-10-93 12:32 FM 6136460997 03 6400997

** SE	ND ***			DURATION	#PAGES	MODE	RESULTS
No	REMOTE STATION	START			0		COMMUNICATION ERROR
1	055 267230	28-10-93	12.30 PM		L		9600
		G3S:0 RHP:0	G3R:0 LG0:0	ECM THP		CSI:1 W/B:74	CIG:0 EQL:08

VERSION: KM1=X01.09 KM2=R01.09 KSP= 02.00 KCP=R04.03

VERSIO	N: KM	1=X01.09	KM2=	R01.	09 KSP=	02.00	KCP=R04. 03
APSE		LOCAL			REMOTE	FCF	FIF
	7 16 35				CED 2100HZ NSF	20	00000580004EB80008252020202020202020202020202020 20006000180B 3033323736322035353020202020202020202020
4 5	-35 -05			-	CSI	40 80 43	004EB800
0 7	-29 -05	TSI DCS TRN	↑ ↑↑↑			83	0046A800
1 7	-67 -67	TRN TCF TCF	$\overrightarrow{\Rightarrow}$			24	Motsubishi machine /Pailed to respond to
10	56 85	TRN TRN		-	CFR		failed to respond to
. 33	2"11	PIX PIX	111111 1			2F	2 mitsubishi machine Locked
3 8	3"88 8"32 2"77	EOP EOP	$\stackrel{\cdot}{\rightarrow}$			2F 2F ERRO	OR SBIOS UP FOR 2 MINITES INSTEAD
41	6-18 7-29	* DCN	\rightarrow			FB	OF TIMENTE OUT AFTER 9 Second
-							

At Mitenbishi 3-11. NG

PROTOCOL MONITOR

K03752

DATE/TIME LOCAL TERMINAL ID. LOCAL TERMINAL NAME COMPANY LOGO 28-10-93 12:09 PM 6136400997 03 6400997

	FCEIVE ***	START TIM	4E	DURATION	#PAGES	MODE	RESULTS
OF	REMOTE STATION			1:02"	1		COMPLETED
1	055 267230	28-10-93 12	:06 PM	1 02	L		9600
		1				001:1	C19:0
	COM . O	G3S:0 G3R:0 RHP:0 LGO:0		ECM THP		CSI:1 W/B:74	EQL:08
	CFG:4	1111					/

VERSION: KM1=X01.09 KM2=R01.09 KSP= 02.00 KCP=R04.03

NEKSTON . V	M 1-701. 0	• 100000		
LAPSE	LOCAL	REMOTE	FCF	FIF
2"35 6"47	CEU NSF	\Rightarrow	20	00001917C0A0DEC1C081F9D8A4A081010A373939303U345620 3330
7"42 8"18 10"48 11"19 11"47	CSI DIS	→ TSI ← DCS ← TRN ← TRN	40 80 43 83	00CEE804 3033323736322035353020202020202020202020 0006A800
11"69 11"69 12"96 13"22 14"26 15"59	* CFR	←- TCF ← TCF -→ ← PIX	EQM 84	Missubishi to my XEREX. Received a piece of paper
33"03 35"58 37"21 39"19	MCF	← PIX ← EOP ← DCN	2F 3C FB	Received a present of frank) XEROX Telecopier 7017

Although the page was error free, it did not terminate correctly & did not have any information on it.

Proje received

