

attached message on the 28th March. The attached message indicates that the problem did lie in the RCM and has been fixed. This was confirmed in a subsequent conversation with [REDACTED]



[REDACTED]

K00941

From: [REDACTED]
To: [REDACTED]
Cc: [REDACTED]
Subject: FW: CAPE1.DOC
Date: Monday, March 28, 1994 5:11PM
Priority: High

Grant,
Do you want any more on this RCM problem? [REDACTED] seems to have solved the problems and whilst the poor setting up of the supervisory system is a worry, I doubt if many new systems will be installed on copper bearers.

[REDACTED]

From: [REDACTED]
To: [REDACTED]
Cc: [REDACTED]
Subject: CAPE1.DOC
Date: Monday, March 28, 1994 3:04PM
Priority: High

Please find attached the results of testing of problems with Cape Bridgewater RCM system . This is additional information to that provided by Mark Hooper on 23-3-94.

I hope this assists.

<<File Attachment: CAPE1.DOC>>

[REDACTED]

1A

Pendlebury, Bruce

From: Gamble, Peter
To: Pendlebury, Bruce
Cc: [REDACTED]
Subject: FW: CAPE1.DOC
Date: Tuesday, 26 April 1994 3:12PM

K00940

Bruce, for information.

Following a call from Alan Smith, I have just had a discussion with Les Churcher re a complaint that Alan Smith lodged earlier today (Leopard No 384 808). I described to Les more accurately what the problem is and he will discuss my comments with Alan Miles.

Peter:

From: Gamble, Peter
To: [REDACTED]
Cc: [REDACTED]; Black, Stephen; Rumble, Paul; [REDACTED]
Subject: RE: CAPE1.DOC
Date: Tuesday, 26 April 1994 2:33PM

John, thanks for the response.

I should have chased it up earlier, but I was on leave.

I am concerned to note that heat may be part of the problem. I had occasion earlier this year to get involved in another 'ongoing' case involving an RCM with a heat problem at Murrumbateman (just outside Canberra). Although the problems experienced by the customer were different, as was the nature of the technical problem, the root cause seems to have been the same - viz heat.

I do note, however, that one of the symptoms from the Murrumbateman case was "Not Receiving Ring", something Alan Smith at Cape Bridgewater has been complaining about for some time.

Peter.

From: [REDACTED]
To: Gamble, Peter
Subject: FW: CAPE1.DOC
Date: Tuesday, 26 April 1994 1:09PM
Priority: High

Peter

Please see reply from Bob Braid. I don't know why you did not get a copy but I will follow up

Do you need anything else.

Regards

From: [REDACTED]
To: Gamble, Peter
Cc: [REDACTED]
Subject: FW: CAPE1.DOC
Date: Tuesday, April 26, 1994 12:40PM
Priority: High

Peter.

Reference your Mail message enquiring about the status of the DNF at Cape Bridgewater, I sent the